

FIG. 1




FIG. 2




FIG. 3




FIG. 4A






FIG. 4B





## NON-DESTRUCTIVE DIAGNOSTIC APPARATUS FOR IDENTIFYING DEFECT TYPE IN CORE COMPOSITE STRUCTURES

Applicant: David Schmaling; Attorney docket 67,008-080;S5643 Express Mail No. EV221422747US

